

Gateway Pedestrian Bridge Houlton, Maine

Sewall recently completed a visual inspection of the timber Gateway Pedestrian Bridge located over the Meduxnekeag River in Houlton, Maine. The visual inspection included reviewing the superstructure, substructure, and deck condition, and underside of the bridge. The structural field review assessed user safety (railings and deck surface) and structural integrity (abutments, primary timber members, repair areas, secondary members and connections).

